

Reserve Repack Report

Report #: 202666

Report Date: 21/11/2019

Date In: 19/11/2019

Pilot : Rich Parton

Telephone: Job 73

Email:

Reserve: Ozone, Angel, 140

Serial AN14-T25A052

DOM 26/07/18

Harness: Ozone oxygen2

Serial OXY2-L-T29C-088

DOM 21/07/18

Deployment Bag: Ozone Angel

Serial N/A

DOM 26/07/18

DISASSEMBLY

Tool Count

Yes No N.A

Check Deployment

Yes No N.A

Steerable designs: steering toggles within reach

Yes No N.A

Bridle Routing

Yes No N.A

Safety notice check: canopy, deployment bag and harness

Yes No N.A

Manufacturer's manual for parachute, container and harness

Yes No N.A

INSPECTION

Deployment Bag : grommets, bungee cord, closure loop

Servicable Not Servicable N.A.

Deployment Bag : handle, sewing reinforcement

Servicable Not Servicable N.A.

Deployment Bag : locking pin(s)

Servicable Not Servicable N.A.

Canopy size (manufacturer's canopy data stamp / measured fabric area)

37 sqm

Canopy max all up weight (manufacturer's canopy data stamp / calculated)

140kg

Canopy condition, material, seams and stitching

Servicable Not Servicable N.A.

Canopy fabric strength : thumb test

Servicable Not Servicable N.A.

Suspension lines : condition, stitching and attachment method

Servicable Not Servicable N.A.

Bridle length (hg) / overall length (pg)

8750mm

Bridle / Risers serviceability, stitching, swivels

Servicable Not Servicable N.A.

Connectors : tightness, condition, strength

Servicable Not Servicable N.A.

Harness container : grommets, webbing, stitching and material

Servicable Not Servicable N.A.

Harness : attachment points

Servicable Not Servicable N.A.

REASSEMBLY

Canopy packed according to manufacturer's manual / BHPA method

Yes No N.A

Deployment bag : size, mouthlock tension

Servicable Not Servicable N.A.

Canopy is acceptable fit in harness container

Yes No N.A

Pin and ring closure systems : a) harness container closure pin(s)

Servicable Not Servicable N.A.

b) locking pins release before tension is placed on the deployment bag

Yes No N.A

Velcro closure systems : a) velcro not clogged or worn

Yes No N.A

b) deployment bag can be extracted with a single movement

Yes No N.A

Check bridle routing

Yes No N.A

Deployment handle : correct side, accessible

Yes No N.A

Accidental deployment stretch check

Yes No N.A

Check parachute does not interfere with any control movement (eg speed bar)

Yes No N.A

Pull check

Yes No N.A

Check Tool Count

Yes No N.A

In the personal opinion of the Packer, the equipment at the time of examination was considered to be Fit Yes No N.A

Repackers Notes : One O ring replaced on shoulder attachment.

Whilst the equipment has been inspected with all reasonable care, the opinion expressed by the Inspector does not give or imply a guarantee that the equipment is free from defects other than those identified above.

Inspected By *Joly*

Owner's Signature

THE FLIGHT PARK Ltd
Braithwaite Farm
Keswick
CA12 5RY
017687 78825
service@theflightpark.com

21/11/2019